


Public Bathing Place Inspection Form							
Bucks County Department of Health 1282 Almshouse Road Doylestown, PA 18901 (215) 345-3318			Date of Inspection Travel Time Arrival Time Inspection Time		06/23/2021 00.2 Hours 12:10 PM 01.4 Hours	Total Violations Registration Expiration Facility Closure Electrical Cert. Expiration	1 04/30/2023 N/A 02/11/2023
Bathing Facility Name Lower Makefield Township Community Pool		Address 1050 Edgewood RD			City State Yardley, PA	Zip Code 19067	
Facility ID # 20B174		Owner Lower Makefield Township			Telephone (215) 493-3020	Purpose of Inspection Initial	
Identification of Violations of the Bucks County Department of Health Rules and Regulations Governing Public Bathing Places							
Item	Wt.	Out	Item	Wt.	Out	Reason For Closure	
<b>GENERAL PROVISIONS</b>							
01 (2.1) Posting Regulations; BCDH Regulations, Registration	1		20 (10.4,10.5,10.6) Overflow and Bottom Cleaning; Directional Color Flow Arrows, Filtration Equipment	1		<input type="checkbox"/> a) Contaminated Water <input type="checkbox"/> b) No current electrical certificate <input type="checkbox"/> c) Pool filters not operating/not turned on <input type="checkbox"/> d) Unsatisfactory disinfection residual <input type="checkbox"/> e) Poor clarity <input type="checkbox"/> f) Fecal or vomiting incident <input type="checkbox"/> g) Other	
* 02 (2.2) Management: Drain Covers in Place, Pool Equipment Maintained	5		21 (10.7) Flow Meters: Installed and Operating	2			
* 03 (2.3) Sewage Disposal: Backwashing and Waste Disposal	5		<b>WATER CLARITY</b> * 22 (11.1) Clarity	5			
04 (2.4) Vector Control: Effective Measures of Control	3		<b>LIFESAVING EQUIPMENT</b> 23 (12.1) Lifesaving Devices, First Aid Kit	3			
05 (2.5) Food Services: Approved and/or Licensed	2		<b>WATER QUALITY</b> 24 (13.1) Bacteriological, Sampling	3			
06 (2.6) Garbage and Refuse: Storage Collection, Disposal	2		25 (13.2) Chemical and pH	3			
<b>HYGIENE REQUIREMENT</b> 07 (4.1,4.2,4.3,4.4,4.5) Personal Items: Suits, Towels, Soap, Sanitary Conditions	2		<b>DISINFECTION</b> * 26 (14.1) Disinfection Equipment, NSF Approved: Properly Installed & Operational, Concentrators	4			
<b>BATHING PLACE CLOSURES</b> * 08 (5.1) Immediate Closures	5		<b>DISINFECTANT EQUIPMENT</b> 27 (15.1) Gas Chlorination: Gas Masks, Fans, Cylinders Secured	2			
<b>ELECTRICAL SAFETY</b> 09 (6.1,6.2,6.3,6.4,6.5,6.6) Code, Wiring, Conductors	2		28 (15.2,15.3,15.4) Equipment Access: Installed Properly, MSDS Sheets, Solution Tanks	1			
10 (6.7) Mechanical Equipment Access	1		<b>BACTERIOLOGICAL AND CHEMICAL QUALITY</b> 29 (16.1,16.2) Certified Labs: Sampling Requirements, Monitor Chlorine, pH and Temperature	2			
* 11 (6.8) Electrical Inspections, Valid Electrical Certificate	5		<b>REPORT OF WATER QUALITY TESTS</b> 30 (17.1) Laboratory Results and Operational Logs	2			
12 (6.9) Lighting Properly Installed	2		<b>LIFEGUARDS (IF REQUIRED)</b> * 31 (18.1,18.2,18.3) Lifeguards Adequate Number, Advantageous Positions, Qualifications	5			
<b>WATER SUPPLY</b> * 13 (7.1) Water Quality: Complies with Chapter 109 Safe Drinking Water Act	5		32 (18.5) Condo and Residential Owner Associations, Private Swim Clubs; Posting Warning Signs, No Lifeguard	1			
14 (7.2) Water supply source: Approved no cross connections	3		<b>REPORTING DISEASE AND INJURY</b> 33 (19.1,19.2) Swimming Injury: Disease Reporting, Properly Submitted	2			
<b>CERTIFICATE OF REGISTRATION</b> * 15 (8.1) BCDH Registration	5		<b>PUBLIC NOTICE</b> 34 (21.1,21.2,21.3) Public Information: Hot Tubs and Spas, Vomitus and Fecal Contamination	2		Approved For Certificate Registration- Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
<b>POOL DEPTH MARKERS</b> 16 (9.1,9.2,9.3,9.4) Location and Design: No Diving Areas, Safety Rope	2		<b>DIVING FACILITIES, STARTING BLOCKS, SLIDES</b> 35 (22.1,22.2,22.3) Diving, Starting Blocks: Slides: Properly Maintained	1		Plant Description Record Review- Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	
<b>CIRCULATION AND FILTRATION</b> 17 (10.1) Adequate Circulation	3		<b>STAIRS, LADDERS AND DECKS</b> 36 (23.1,23.2,23.3) Stairs, Ladders and Decks: Properly Installed and Maintained	2	X	Food Service Provided- Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Food Service Inspected- See Food Facility Inspection Form Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
18 (10.2) Recirculation and Filtration	2		<b>OTHER PERMITS AND CERTIFICATIONS</b> 37 (24.1,24.2,24.3) Construction Permit: Certification to Operate, On File, Pesticide Certification: In Compliance, Referred	2		<b>ADDITIONAL REMARKS</b> See Remarks on attached sheets <input type="checkbox"/>	
19 (10.3) Turnover Periods	2						

<b>Follow Up</b> Yes... <input type="checkbox"/> No... <input checked="" type="checkbox"/>	<b>Rating Score</b> 100 less weight of items violated → <span style="border: 1px solid black; padding: 2px;">98</span>	<b>Laboratory Name:</b> Analytical Laboratories, Inc.	Received by: <u>Sam Ferris</u> Name Title Inspected by: _____ Name Title
--	---	--	---

\* Critical Items Requiring Immediate Attention

**INSPECTION ITEM  
NARRATIVE DESCRIPTION**

FACILITY NAME Lower Makefield Township Community Pool		INSPECTION DATE 06/23/2021	FACILITY I.D. 20B174
ITEM NO	REMARKS	TO BE CORRECTED BY	
(36)	Right-side railing at the Lap Pool entrance is not properly secured to the entry steps. Secure railing. New Violation.	06/24/2021	
General Comments			
"Diving Pool" on report corresponds with facility's Lap Pool.			

Received by: 

Inspected by:   
FACILITY